

02658.000700.

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

STEPHEN M. DERSHEM ET AL.

Appln. No.: 10/084,389

Filed: February 25, 2002

For: THERMOSETTING RESIN
COMPOSITIONS CONTAINING
MALEIMIDE AND/OR VINYL
COMPOUNDS

U.S. Patent No.: 6,852,814 B2

Issued: February 8, 2005

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

**CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor


05/06/2005 SSITHIB1 00000080 6852814
01 FC:1811 100.00 OP

character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Lawrence S. Perry
Attorney for Patentees
Registration No. 31,865

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY_Main 497959v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,852,814 B2

DATED : February 8, 2005

INVENTOR(S) : STEPHEN M. DERSHEM ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [73]:

Assignee, "Henkel Corporation, CT (US)" should read --Henkel Corporation,
Rocky Hill, CT (US)--.

COLUMN 5:

Line 40, "with in" should read --within--.

COLUMN 8:

Line 49, "with in" should read --within--.

COLUMN 9:

Line 4, "with in" should read --within--.

COLUMN 19:

Line 42, "Ag coated" should read --Ag-coated--.

COLUMN 20:

Line 15, "Ag" should read --Ag--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,852,814 B2No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,852,814 B2

DATED : February 8, 2005

INVENTOR(S) : STEPHEN M. DERSHEM ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21:

Line 18, "one minute" should read --one-minute--; and

Line 46, "comprising" should read --, comprising:--.

COLUMN 22:

Line 3, "a Ag coated" should read --an Ag-coated--;

Line 9, "comprising" should read --, comprising:--; and

Line 39, "composition" should read --assembly--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,852,814 B2

No. of add'l. copies
@ 30¢ per page

